


Brushing Requirements

FOR TRANSMISSION LINES



- 1) All trees, limbs, deadfall and brush are to be removed between brushing lines indicated.
- 2) Limbing must be completed to the top of trees at the brushing line or the tree must be removed.
- 3) All stumps are to be cut flush or as close as possible to the ground, not to exceed 100 mm from ground level.
- 4) All trees leaning toward the brushed right-of-way are considered "danger trees" and must be removed (see Tree B in diagram).
- 5) All dead or rotting trees adjacent to the right-of-way must be removed.